



TECHNICAL FIELD BULLETIN



Date February 2004
 Subject NKL Dust Cover and Coin Rack Change
 Issue By NKL Cash Handling - a member of FKI Security Group
 Issue To Authorized Factory Service Personnel
 Document 40201

OVERVIEW

In an effort to continually improve quality and gain greater manufacturing efficiency, the dust covers used on the interior side of the outer door of most NKL "Premium" hardware style safes are being changed. Due to the changes to the dust cover, the coin racks used have also changed. In the event that an older dust cover has to be replaced, new coin racks will also be required.

PRODUCTS AND SERIAL NUMBERS AFFECTED

The new parts went into regular production on models BSD292020, BSD322020, BSD412526, BSD472526, AXC292020, AXC322020, starting with Serial Number SP2004004031. These new parts may be retrofitted to above models manufactured since July 2003. Units built prior to serial number SP2003026001 may not be retrofitted with these parts (Contact NKL Technical Support for assistance with older product).

ACTION REQUIRED

Do not replace an existing dust cover with a new dust cover unless the existing dust cover is damaged or missing. When replacing a dust cover, the coin rack(s) must also be replaced. Refer to the chart in the following section for part numbers.

ADDITIONAL INFORMATION

Model	New Dust Cover	Old Dust Cover
BSD292020	700521	10030026
BSD322020	700528	10020026
BSD412526	700529	10010043
BSD472526	700530	10080009
AXC292020	700521	10030026
AXC322020	700528	10020026

New coin rack assembly 600351 replaces old style assembly 10000176 (quantity varies by model).

