



# TECHNICAL FIELD BULLETIN



Date July 2004  
Subject XLV Version 3.35 Released  
Issue By NKL Cash Handling - a member of FKI Security Group  
Issue To FKI Sales, Field Service & Technical Support; Service Partner Network  
Document 40707

## PRODUCTS AFFECTED

Autobank and Intellisafe products with XLV Electronics. First S/N manufactured with Version 3.35 is SP2004030002

## OVERVIEW

The software change corrects issues from previous releases. There are no new features with this release. It is not necessary to upgrade existing products unless specifically directed by NKL Technical Support.

## ACTION REQUIRED

Due to recent (nearly concurrent) change to CPU hardware (newest hardware is marked "Rev C"), if it is necessary to update a CPU the entire CPU assembly should be changed out with new hardware that includes new software. Updating the CPU should only be done under the specific direction of NKL Technical Support.

## ADDITIONAL INFORMATION

Refer to the Procedures for Updating Software and the Autobank Service Manual for additional printed instructions. For more information call NKL Technical Service at 1-800-452-4655.