



TECHNICAL FIELD BULLETIN



Date February 2009
Subject D8C Vend Board Update
Document 90202-1045

OVERVIEW

Due to slower vend motors being used in production it has become necessary to modify software code on the main vend board. The updated code allows more time for rotors to reach their end of travel and home positions. The result is elimination of false tube jam errors. It also allows improves the ability of the safe to align motors when the safe powers up.

PRODUCTS AND SERIAL NUMBERS AFFECTED

NKL D8C safes with AuditLok XLV electronics starting with S/N SP2008049032. The main vend board part number is 1505310C. The updated board will appear on the configuration report as Vend Version 0.66.

ACTION REQUIRED

Existing units in the field should not be updated with a new main vend board unless the safe suffers repeated tube jams or rotor alignment problems.

ADDITIONAL INFORMATION

If you have any questions contact NKL Technical Service at 1-800-452-4655.