



IMAGE TECHNICAL VAULT FIELD BULLETIN



Date December 2005
Subject Microsoft Security Bulletin Analysis for October 2005
Issue By Image Vault LLC. - a member of FireKing Security Group
Issue To Image Vault Sales and Service
Document 51202

OVERVIEW

The Microsoft Security Bulletin is a monthly list of all XP security patches. The Microsoft Security Bulletin Analysis for October 2005 yielded one required update for XP Embedded-based Image Vault recorders.

PRODUCTS AFFECTED

All Image Vault DVRs with Version 8.0 or higher software.

ACTION REQUIRED

Download the patch from <http://www.image-vault.com/download> (Titled: October 2005 Security Patch). Using the Remote Update feature of IVPlay, update your DVR.

ADDITIONAL INFORMATION

For any additional questions, concerns or to obtain a copy of the complete report contact Image Vault Technical Service at 1-888-462-4382